

2016 - 2021 Cadillac ATS-V -CTS-V - CT4-V: Service Bulletin: #18-NA-285: Information on Slight Movement in Park at Ignition On and Vehicle Start Up and/or During a Remote Vehicle Start Event - (Jan 22, 2021)

#18-NA-285: Information on Slight Movement in Park at Ignition On and Vehicle Start Up and/or During a Remote Vehicle Start Event - (Jan 22, 2021)

Subject: Information on Slight Movement in
Park at Ignition On and Vehicle Start
Up and/or During a Remote Vehicle
Start Event

This bulletin replaces PIP5293A. Please discard PIP5293A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmi ssion:
		from	to	from	to		
Cadillac	ATS	2016	2019	—	—	—	(8 Speed A utomati c)
	CTS						M5U, M5N
	CT4	2020	2021				M5N
	CT6	2016	2018				M5N,

				M5X
	Escalade Models	2015	2017	M5U
Chevrolet	Camaro	2016	2021	M5T, M5U
	Colorado	2017	2021	M5T
	Corvette	2015	2019	M5U
	Express	2017	2021	M5U MQD
	Silverado Models	2015	2018	M5U, M5X
	Silverado 1500 (New Model)	2019	2019	M5U M5X MQE
	Silverado 1500	2020	2021	
GMC	Canyon	2017	2021	M5T
	Savana	2017	2021	M5U MQD
	Sierra Models	2015	2018	M5U, M5X
	Sierra 1500 (New	2019	2019	M5U M5X MQE

Model)

Sierra 2020 2021
1500

Yukon 2015 2017
Models

M5U

Involved Region or Country

North America, Argentina, Brazil, Chile, Guatemala, Peru, Europe, Israel, Middle East, China, Japan, Philippines, Thailand, Cadillac Korea, GM Korea Company

Condition

Some customers may comment that the vehicle may rock or move slightly forward or rearward while in Park at start up and/or when using the remote vehicle start function.

- This condition may be accompanied by a clunk noise.

Cause

This condition may be caused by the application of the 1-2-7-8 Reverse Clutch and the 1-2-3-4-5 Reverse Clutch in addition to residual transmission fluid in the other clutch packs creating a partial apply on start up.

- The movement may be more apparent at Ignition On, during a remote vehicle start.

As the 1-2-7-8 Reverse Clutch and the 1-2-3-4-5 Reverse Clutch are applied at Ignition On, the engine and portions of the transmission are at full idle speed causing the clutches to apply at a quicker rate than during a normal start. This movement is stopped by the park pawl and/or the transmission fluid exhausting completely from the clutch packs.

Correction

This condition is normal and no repairs should be attempted. This can be verified by comparing with another identically built vehicle under the same conditions.

Parts Information

No parts are required for this repair.

Version

2

Modified

Released September 21, 2018

January 22, 2021 – Added the 2020-2021 Model Years, additional Models and updated the Involved Region or Country section.

Online URL:

<https://www.cadillacvnet.com/knowledge-base/article/2016-2021-cadillac-ats->

[v-cts-v-ct4-v-service-bulletin-18-na-285-information-on-slight-movement-in-park-at-ignition-on-and-vehicle-start-up-and-or-during-a-remote-vehicle-start-event-jan-22-2021-50.html](#)