

# 2020 - 2021 Cadillac CT4-V CT5-V: Service Bulletin: #21-NA-091: Information on Normal Rearview Camera Display Operation - Flashing Diamond - Spot - or UFO like image on Rear View Camera Display - (Apr 13, 2021)

## #21-NA-091: Information on Normal Rearview Camera Display Operation - Flashing Diamond - Spot - or UFO like image on Rear View Camera Display - (Apr 13, 2021)

**Subject:** Information on Normal Rear View Camera Display Operation - Flashing Diamond - Spot - or UFO like image on Rear View Camera Display

This bulletin replaces PIT5799A. Please discard PIT5799A.

| Brand:    | Model:       | Model Year: |      | VIN: |    | Engine: | Transmission: |
|-----------|--------------|-------------|------|------|----|---------|---------------|
|           |              | from        | to   | from | to |         |               |
| Cadillac  | CT4          | 2020        | 2020 | —    | —  | —       | —             |
|           | CT5          |             | 2021 |      |    |         |               |
|           | Escalade     |             |      |      |    |         |               |
|           | Escalade ESV |             |      |      |    |         |               |
| Chevrolet | Bolt EV      | 2020        | 2020 |      |    |         |               |
|           | Corvette     |             | 2021 |      |    |         |               |

e

Silverad

o 1500

Silverad

o 2500

HD/350

0HD

Tahoe

Suburba

n

|            |          |      |      |
|------------|----------|------|------|
| <b>GMC</b> | Sierra   | 2020 | 2021 |
|            | 1500     |      |      |
|            | Sierra 2 |      |      |
|            | 500HD/   |      |      |
|            | 3500H    |      |      |
|            | D        |      |      |
|            | Yukon    |      |      |
|            | Yukon    |      |      |
|            | XL       |      |      |

***Involved Region or Country***

North America, Uzbekistan, Russia, Middle East, Israel, Palestine, Chile, Colombia, Ecuador, Paraguay, Peru, Korea, Thailand, Brazil

***Additional Options (RPOs)***

Equipped with UVI, UVS or UV2

***Condition***

Some customers may comment on a flashing light present on the radio display when in Reverse and with the rear view camera on, usually is

corrected by an ignition cycle.





*Correction*

Please communicate to the customer that the rear view camera system and radio display are functioning as designed and this is a normal condition of their vehicle. Please share this information with the customer, including a copy of this bulletin.

Technicians should verify that no other conditions are present and return the vehicle to the customer.

*Version*

1

*Modified*

Released April 13, 2021

Online URL:

<https://www.cadillacvnet.com/knowledge-base/article/2020-2021-cadillac-ct4-v-ct5-v-service-bulletin-21-na-091-information-on-normal-rearview-camera-display-operation-flashing-diamond-spot-or-ufo-like-image-on-rear-view-camera-display-apr-13-2021-62.html>